

PALMADEQ CORP.
DRIVER'S VEHICLE INSPECTION REPORT

Office Location: VENTURA

Odometer: _____

Date 04/24/2025

	YES	NO	N/A
Mirrors	☒	☐	☐
Windows	☒	☐	☐
Tires, Wheels and Lugs	☒	☐	☐
Fuel Tank and Caps	☒	☐	☐
Bumper intact	☒	☐	☐
Oil Level	☒	☐	☐
Radiator/Coolant level	☒	☐	☐
Windshield Washer Level	☒	☐	☐
Battery	☒	☐	☐
Hoses and Belts intact	☒	☐	☐
Oil Pressure	☒	☐	☐
Flashers	☒	☐	☐
Fuel Guage	☒	☐	☐
Horn	☒	☐	☐
Windshield Wipers	☒	☐	☐
Heather/ Defroster	☒	☐	☐
Steering Wheel	☒	☐	☐
Parking/emergency Brake	☒	☐	☐

	YES	NO	N/A
Headlights	☒	☐	☐
Turn Signals	☒	☐	☐
Flashers	☒	☐	☐
Tail Lights	☒	☐	☐
Brake Lights	☒	☐	☐
Supplies:			
Nylon Cargo Tie-Downs	☒	☐	☐
Fire Extinguisher	☒	☐	☐
Triangle Reflectors	☒	☐	☐
First Aide Kit	☒	☐	☐
Eye Wash Bottle	☒	☐	☐
Gloves and alcohol gel	☒	☐	☐

Driver's Name: BECERRA, JESSE

Condition of above vehicle is satisfactory: Yes ☒ No ☐

Above noted defects corrected - Date _____



×

Supervisor's Signature

04/24/2025

DATE



×

Driver's Signature

04/24/2025

DATE