# PALMADEQ CORP.
# DRIVER'S VEHICLE INSPECTION REPORT

Office Location: COVINA  Odometer:  Date 05/07/2025

| | YES | NO | N/A |
|---|---|---|---|
| Mirrors | ☑ | ☐ | ☐ |
| Windows | ☑ | ☐ | ☐ |
| Tires, Wheels and Lugs | ☑ | ☐ | ☐ |
| Fuel Tank and Caps | ☑ | ☐ | ☐ |
| Bumper intact | ☑ | ☐ | ☐ |
| Oil Level | ☑ | ☐ | ☐ |
| Radiator/Coolant level | ☑ | ☐ | ☐ |
| Windshield Washer Level | ☑ | ☐ | ☐ |
| Battery | ☑ | ☐ | ☐ |
| Hoses and Belts intact | ☑ | ☐ | ☐ |
| Oil Pressure | ☑ | ☐ | ☐ |
| Flashers | ☑ | ☐ | ☐ |
| Fuel Guage | ☑ | ☐ | ☐ |
| Horn | ☑ | ☐ | ☐ |
| Windshield Wipers | ☑ | ☐ | ☐ |
| Heather/ Defroster | ☑ | ☐ | ☐ |
| Steering Wheel | ☑ | ☐ | ☐ |
| Parking/emergency Brake | ☑ | ☐ | ☐ |

| | YES | NO | N/A |
|---|---|---|---|
| Headlights | ☑ | ☐ | ☐ |
| Turn Signals | ☑ | ☐ | ☐ |
| Flashers | ☑ | ☐ | ☐ |
| Tail Lights | ☑ | ☐ | ☐ |
| Brake Lights | ☑ | ☐ | ☐ |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| **Supplies:** | | | |
| Nylon Cargo Tie-Downs | ☑ | ☐ | ☐ |
| Fire Extinguisher | ☑ | ☐ | ☐ |
| Triangle Reflectors | ☑ | ☐ | ☐ |
| First Aide Kit | ☑ | ☐ | ☐ |
| Eye Wash Bottle | ☑ | ☐ | ☐ |
| Gloves and alcohol gel | ☑ | ☐ | ☐ |

Driver's Name: SORIANO, ALEX

Condition of above vehicle is satisfactory: Yes ☑ No ☐

Above noted defects corrected - Date 

× 

**Supervisor's Signature**

05/07/2025

**DATE**

× 

**Driver's Signature**

05/07/2025

**DATE**